

December 30, 2009



U.S. Department  
of Transportation

East Building, PHH-30  
1200 New Jersey Avenue S.E.  
Washington, D.C. 20590

**Pipeline and Hazardous  
Materials Safety Administration**

DOT-SP 10751  
(NINETEENTH REVISION)

(FOR RENEWAL, SEE 49 CFR § 107.109)

1. GRANTEE: (See individual authorization letter)
2. PURPOSE AND LIMITATION:
  - a. This Special Permit authorizes the transportation in commerce of certain Division 1.1, 1.4 and 1.5 explosives, Division 5.1 oxidizers and combustible liquids in separate containers mounted on the same vehicle frame structure. This Special Permit provides no relief from the Hazardous Materials Regulations (HMR) other than as specifically stated herein. The most recent revision supersedes all previous revisions.
  - b. The safety analyses performed in support of this special permit considered only the hazards and risks associated with transportation in commerce.
  - c. Unless otherwise stated herein, this special permit consists of the special permit authorization letter issued to the grantee together with this document.
3. REGULATORY SYSTEM AFFECTED: 49 CFR Parts 106, 107 and 171-180.
4. REGULATIONS FROM WHICH EXEMPTED: 49 CFR § 177.835(c)(3) in that Division 1.1 and 1.5 materials may not be carried on any vehicle in combination with a cargo tank required to be marked or placarded under § 177.823, §§ 177.848(d) and 177.848(e)(2) in that transportation of Division 1.1 and 1.5 explosives may not be shipped together with Division 5.1 liquids, and § 177.848(g)(3) in that Compatibility Group B detonators may not be carried on the same motor vehicle as Compatibility Group D explosives, except as specified herein.

December 30, 2009

5. This special permit is based on the responses to the Pipeline and Hazardous Materials Safety Administration's (PHMSA) show cause letter issued under § 107.121 initiated on August 14, 2008.
6. HAZARDOUS MATERIALS (49 CFR § 172.101):

Hazardous Materials Description			
Proper Shipping Name	Hazard Class/ Division	Identification Number	Packing Group
Ammonium nitrate emulsion	5.1	UN3375	II
Boosters, without detonator	1.1D	UN0042	II
Combustible liquid, n.o.s. (contains No.2 fuel oil and organic emulsifiers)	Combustible	NA1993	III
Cord, detonating, flexible	1.1D	UN0065	II
	1.4D	UN0289	II
Detonators, electric, for blasting	1.1B	UN0030	II
	1.4B	UN0255	II
Detonator assemblies, non-electric	1.4B	UN0361	II
Explosive, blasting, type E or Agent blasting, type E	1.5D	UN0332	II
Ammonium nitrate	5.1	UN1942	III
Oxidizing liquid n.o.s. (Contains ammonium, sodium and/or calcium nitrates)	5.1	UN3139	II

**NOTE:** Other blasting explosives and oxidizers must be specifically identified to, and acknowledged in writing by, the Office of Hazardous Materials Special Permits and Approvals (OHMSPA) prior to the first shipment.

**December 30, 2009**

7. SAFETY CONTROL MEASURES:

a. PACKAGING - Prescribed packagings are as follows:

(1) Division 1.1D and 1.4D explosives must be packaged as prescribed in the § 173.62(c) Table according to their UN number and overpacked in an IME Safety Library Publication 22 (IME-22) container.

(2) Division 1.1B and 1.4B electric detonators and non-electric detonator assemblies must be packaged according to § 173.63(f) or (g) in a separate IME 22 container.

(3) Bulk Division 1.5D blasting explosives, 5.1 oxidizing liquid, n.o.s. and ammonium nitrate must be transported in either specification or non-specification aluminum cargo tanks and/or cargo bins which have been identified to and acknowledged, in writing, by OHMSPA prior to the first shipment.

(4) Non-specification cargo tanks must be equipped with pressure relief systems meeting the requirements of §§ 178.346-3 or § 178.347-4.

(5) Combustible liquids must be contained in at least 1/8 inch thick aluminum chassis-mounted saddle tanks not exceeding 300 gallons capacity and meeting all Federal Motor Carrier Safety Administration side-mounted fuel tank requirements.

b. OPERATIONAL CONTROLS -

(1) IME-22 container(s) or compartment(s) must be located directly behind the cab or at other locations entirely within the profile of the vehicle, forward of the rear most axle, and may not be located on the front of the vehicle. The IME-22 container(s) or compartment(s) may not share a common wall or be in direct contact with any cargo tank, tank bin, pump or piping containing a hazardous material.

(2) The saddle tanks must be mounted between the cab and the cargo area and below the IME 22 magazine compartment and completely segregated from the rear cargo compartments containing tanks and/or bins of Division 1.5D blasting explosives and/or Division 5.1

**December 30, 2009**

oxidizers.

(3) Spillage, waste or residual accumulations of Division 1.5D blasting explosives and/or 5.1 oxidizers and/or any combustible liquids anywhere in the vehicle should be cleaned up immediately and properly handled for disposal.

(4) All transfer pumps must be equipped with at least two positive means to prevent operation while in transportation. All process lines should be appropriately cleaned to minimize residue prior to transport on public roads and highways and valves shall be securely closed before transport on a public road or highway.

(5) All other process lines, discharge lines, chutes, surge hoppers, pumps or augers should be appropriately cleaned to the extent practicable to minimize residue prior to transport on public roads or highways.

(5) Driver Qualification and Training Program Audits. By July 1, 2010, and annually thereafter the special permit grantee must audit its program to validate the qualifications and training of the persons who operate the vehicles authorized under the terms of the special permit. The records of the audit must be maintained for one year or until the next annual audit. The audit must ensure:

(i) Each driver holds a Commercial Driver's License and appropriate endorsements, as required by 49 CFR Part 383, and meets the qualification requirements in 49 CFR Part 391.

(ii) Each driver has received current training as required by 49 CFR part 172, Subpart H, and 49 CFR §§ 177.800 and 177.816. This training must specifically include the terms and conditions of the special permit(s); design and operational characteristics of the vehicles authorized under these special permits; methods of defensive driving and vehicle control to avoid accidents (including roll-overs) and how to recover control in the event the wheels leave the paved surface of the road; successful road tests in a vehicle similar to the one they will operate prior to being authorized to operate a vehicle under the

**December 30, 2009**

terms of this special permit and emergency response procedures including information necessary to communicate to responders in the event of an incident. Training records must be maintained as required by 49 CFR part 172, Subpart H.

(6) Training after an accident. Beginning July 1, 2010, a driver of a vehicle operated under the terms of this special permit that is involved in a "preventable" accident, as described in 49 CFR Part 385, Appendix A, must be retrained in accordance with the applicable provisions of paragraph 7.b.(5)(ii) above prior to resuming operations of a vehicle operated under the terms of this special permit. Note that if the vehicle is not disabled as a result of the preventable accident, the driver may complete the assigned movement for the vehicle.

(7) Vehicle Inspections.

(i) By July 1, 2010, and annually thereafter the special permit grantee must perform an audit of its program for vehicle inspections to ensure that the requirements for daily and periodic inspections set forth in 49 CFR Part 396 are properly performed and recorded. A record of the audit must be maintained for a minimum of one year or until the next annual audit.

(ii) Tire Inspections

(A) The grantee must ensure that tires installed on a vehicle authorized under the terms of this special permit are rated and sized according to the tire manufacturer's recommendations for size and gross vehicle weight rating, as displayed on the sidewall of the tire.

(B) Tires that are more than six years old, based on the manufacture date marked on the sidewall of the tire, may not be used on vehicles authorized under this special permit.

(C) Tires on the steering axle must have a minimum tread depth of 8/32 inch and may not

**December 30, 2009**

be retreaded tires. All other tires on the vehicle must have a minimum tread depth of 4/32 inch.

(D) Tire Pressure. When vehicles authorized under this special permit are in use, tire pressure must be monitored using one of the following methods:

(1) Tire pressure must be measured and recorded as a minimum on a daily basis and additionally each time the vehicle begins a trip on a public roadway. Tire pressure must be adjusted if it is more than 25% below the recommended inflation pressure. The results must be recorded in the vehicle inspection report as required in 49 CFR 396.11, or

(2) Tire pressure must be physically measured and recorded at least once in each consecutive seven-day period, and electronic or mechanical pressure monitoring systems must be installed and functional on all wheels. Tire pressure must be adjusted if it is more than 25% below the recommended inflation pressure. The results must be recorded in the driver vehicle inspection report as required in 49 CFR 396.11.

(3) Flat, leaking, or improperly inflated tires must be repaired, replaced, or properly inflated before the vehicle is driven or at the nearest safe location.

(E) Prior to traveling on a public roadway, tires must be inspected to ensure they conform to requirements in the North American Standards of the Commercial Vehicle Safety Alliance. However, tread depth must meet the minimum requirements of paragraph 7.b.(7)(ii)(C). Tires that meet the out-of-service criteria must be replaced prior to the vehicle being used on a public roadway.

**December 30, 2009**

(8) Vehicle Batteries.

(i) By January 1, 2011, each vehicle operating under the terms of this special permit must be equipped with a redundant system capable of shutting off all mechanical and electrical systems in the event of a rollover incident or incident when truck is in upright position. The system must be clearly marked and be tested every month and repaired or replaced if the test indicates a malfunction.

(ii) By January 1, 2011, batteries and housings must be located towards the front of the vehicle, within the profile of the vehicle, and marked in such a way as to be easily identified to emergency responders. The battery housing must be designed to meet the requirements of 49 CFR 393.30 with the additional requirement that all cables, not just those leading to the starter motor, must be protected and that the positive (+) battery terminal must be covered to prevent the possibility of short circuit.

(9) Emergency Response.

(i) By July 1, 2010, the grantee must develop, maintain, and implement an emergency response action plan that at a minimum describes the risks associated with the transportation of the materials listed in paragraph 6 of this special permit on the same transport vehicle, including risks resulting from the accidental mixing of these materials as a result of a breach or breaches in the containment systems on the transport vehicles, especially when a fire is involved, and the actions to be taken to minimize such risks. The emergency response action plan must include guidance for first responders concerning actions to be taken in the event of an accident involving the transport vehicle both in the absence of a fire and if a fire results from the accident.

(ii) The emergency response guidance developed as part of the action plan must be maintained on each vehicle operating under the special permit in the manner set forth in 49 CFR § 172.602(c).

**December 30, 2009**

8. SPECIAL PROVISIONS:

a. A person who is not a holder of this Special Permit who receives a package covered by this Special Permit may reoffer it for transportation provided no modification or change is made to the package and it is reoffered for transportation in conformance with this Special Permit and the HMR.

b. A current copy of this Special Permit must be maintained at each facility where the package is offered or reoffered for transportation.

c. MARKING -

(1) Each motor vehicle must be plainly marked on the right side near the front, in letters at least 5 cm (2 inches) high on a contrasting background "DOT-SP 10751".

(2) Each portable tank must be plainly marked on both sides near the middle, in letters at least two inches high on a contrasting background, "DOT-SP 10751".

d. In the event of an accident for which an incident report is required under 49 CFR §§ 171.15 or 171.16 that results in an overturn of a vehicle operated under the terms of this special permit, the special permit grantee must:

(1) Conduct an in-depth investigation to determine the cause of the cause(s) of the accident and provide a report of the investigation's findings, conclusions, and recommendations to prevent future accidents or incidents. The report must be completed within 30 days after the accident or incident and forwarded to OHMSPA within 15 days.

(2) Provide a copy of the insurance company investigation report, if available, and the police report to OHMSPA within 15 days of the date the special permit grantee receives them. If the insurance company investigation report is not available, the special permit grantee must arrange for an independent accident reconstruction investigation to determine the root cause of the incident and any other factors that might be relevant to prevent similar accidents from occurring in the future. The report from the reconstruction and



**December 30, 2009**

the police report must be provided to OHMSPA within 15 days of the date the special permit grantee receives them.

(3) If requested by PHMSA, the grantee must arrange for an independent accident reconstruction investigation to determine the root cause of the incident and any other factors that might be relevant to prevent similar accidents from occurring in the future. The report from the reconstruction must be provided to OHMSPA within 60 days of the PHMSA request to conduct the investigation.

9. MODES OF TRANSPORTATION AUTHORIZED: Motor vehicle.

10. MODAL REQUIREMENTS:

a. A current copy of this Special Permit must be carried aboard each motor vehicle used to transport packages covered by this Special Permit.

b. Drivers must have been instructed as to the necessary safeguards and proper procedures in the event of an unusual transportation delay, fire, explosion or accident involving the hazardous materials covered by this special permit.

11. COMPLIANCE: Failure by a person to comply with any of the following may result in suspension or revocation of this special permit and penalties prescribed by the Federal hazardous materials transportation law, 49 U.S.C. 5101 et seq:

- o All terms and conditions prescribed in this special permit and the Hazardous Materials Regulations, 49 CFR Parts 171-180.
- o Persons operating under the terms of this special permit must comply with the security plan requirement in Subpart I of Part 172 of the HMR, when applicable.
- o Registration required by § 107.601 et seq., when applicable.
- o All applicable requirements in the Federal Motor Carrier Safety Regulations (49 CFR Parts 390-397).

Each "Hazmat employee", as defined in § 171.8, who performs a function subject to this special permit must receive

**December 30, 2009**

training on the requirements and conditions of this special permit in addition to the training required by §§ 172.700 through 172.704.

No person may use or apply this special permit, including display of its number, when this special permit has expired or is otherwise no longer in effect.

Title VII of the Safe, Accountable, Flexible, Efficient Transportation Equity Act: A Legacy for Users (SAFETEA-LU)- 'The Hazardous Materials Safety and Security Reauthorization Act of 2005' (Pub. L. 109-59), 119 Stat. 1144 (August 10, 2005) amended the Federal hazardous materials transportation law (49 U.S.C. 5101 et seq.) to change the term "exemption" to "special permit" and authorize a special permit to be granted up to two years for new special permits and up to four years for renewals.

**December 30, 2009**

12. REPORTING REQUIREMENTS: Shipments or operations conducted under this special permit are subject to the Hazardous Materials Incident Reporting requirements specified in 49 CFR 171.15, Immediate notice of certain hazardous materials incidents, and 171.16, Detailed hazardous materials incident reports. In addition, the grantee(s) of this special permit must notify the Associate Administrator for Hazardous Materials Safety, in writing, of any incident involving a package, shipment or operation conducted under terms of this special permit.

Issued in Washington, D.C.:



for Dr. Magdy El-Sibaie  
Acting Associate Administrator for Hazardous Materials Safety

Address all inquiries to: Associate Administrator for Hazardous Materials Safety, Pipeline and Hazardous Materials Safety Administration, Department of Transportation, Washington, D.C. 20590. Attention: PHH-31.

Copies of this special permit may be obtained by accessing the Hazardous Materials Safety Homepage at [http://hazmat.dot.gov/sp\\_app/special\\_permits/spec\\_perm\\_index.htm](http://hazmat.dot.gov/sp_app/special_permits/spec_perm_index.htm) Photo reproductions and legible reductions of this special permit are permitted. Any alteration of this special permit is prohibited.

PO: Burger